

# Incline roundabout lanes to be altered

The Nevada Department of Transportation will reduce Highway 28 eastbound entering the Incline Village roundabout from two to one lane in an effort to enhance safety.

Currently, two travel lanes are in place on Highway 28 east entering the roundabout intersection with Mount Rose Highway. Beginning July 14, temporary pavement markings will be placed to reduce the eastbound highway to one lane. The traffic configuration will be evaluated and, if effective, could be delineated with permanent roadway striping in the future.

“Traffic roundabouts such as this can be instrumental in reducing severe crashes and helping keep traffic flowing through an intersection,” NDOT District Engineer Thor Dyson said in a statement. “But, we continue to see signs of speeding or unsafe merging into the roundabout. Traffic safety and mobility are our top priorities. For safety, the reduced lanes will be tested as a way to slow speeds and help keep drivers in the roundabout safe and mobile.”

NDOT, in partnership with the Tahoe Transportation District, constructed the \$2.4 million roundabout in 2012.